

MULOR BRIDGE

Interserve Facilities Management Ltd

Fire Safety Management Procedures

1.5.1) Fire Drill Record

Date	Duration	Fire Drill Evacuation Time	Name of Person(s) Receiving Training	Type of Drill or Period of Instruction	Remarks	Signature of Instructor
16/9/14	3 mins	10-45	FULL FIRE DRILL	(EVERYBODY IN SESSION)		ACB
22/15	2 MINS	13-55	FULL FIRE DRILL	FIRE SERVICE ATTENDED (PLANNED VISIT)		ACB
11/6/15	2.2 MINS	10 00	FULL FIRE DRILL		ALL O.K.	ACB
24/6/15		12.45	FIRE ALARM (10-12-13-14-15)			ACB
21/9/15	2 MINS	10.05	FULL FIRE DRILL		ALL O.K.	ACB
29/2/16	2 MIN 45S	1250	FULL FIRE DRILL	LUNCH TIME UNABLE TO HEAR SOUNDBY IN PLAYGROUND		ACB
24/5/16	2 MIN 53S	0930	FULL FIRE DRILL		ALL O.K.	ACB
15/9/16	2.2 MINS	10 10	FULL FIRE DRILL		ALL O.K.	ACB
23/2/17	2 MINS	10 00	FULL FIRE DRILL		ALL O.K.	ACB
22/5/17	2 MINS	1330	FULL FIRE DRILL		ALL O.K.	ACB
25/9/17	2 MIN 10S	0920	FULL FIRE DRILL		ALL O.K.	ACB
7/3/18	3 MINS 20S	13 00	FULL FIRE DRILL	UNABLE TO HEAR ALARM IN FRONT PLAYGROUND		ACB
7/1/19	2 MIN 30S	11 00	FULL FIRE DRILL			ACB
10/9/19	2 MIN 52S	11 05	FULL FIRE DRILL		EXCELLENT	ACB
6/2/19	2 MIN 21S	15 00	FULL FIRE DRILL		EXCELLENT	ACB
25/4/19	3 MIN 30S	10 20	FULL FIRE DRILL		ALL O.K.	ACB
24/9/19	2 MIN 30S	10 00	FULL FIRE DRILL		EXCELLENT	ACB
10/1/20	2 MIN 23S	11 00	FULL FIRE DRILL		EXCELLENT	ACB
12/6/20	1 MIN 48S	11 10	FULL FIRE DRILL		EXCELLENT	ACB
19/6/20	1 MIN 15S	14 05	FULL FIRE DRILL		EXCELLENT	ACB
3/7/20	1 MIN 38S	09 10	FULL FIRE DRILL		EXCELLENT	ACB
10/7/20	2 MIN 03S	10 00	FULL FIRE DRILL		EXCELLENT	ACB
18/9/20	2.48	10.55	"	"	"	ACB
			INFORMED A. DAVIDSON BEING WIDGED, OPEN		REGARDING DECKS DUE TO COVID.	PMU
3/2/21	1 MIN 41 SEC	0950	FULL FIRE DRILL		EXCELLENT	ACB

* NEW GATE INTO PLAYGROUND WILL NEED MODIFYING TO ALLOW ACCESS BOTH WAYS - MODIFIED 14/20 ACB.